

33103-1005
-1010
-1025

MATERIAL SAFETY DATA SHEET

Product Name: Carve & Cast	Product Code: Carve & Cast
Manufacturer's Name: American Art Clay Co., Inc 6060 Guion Road Indianapolis, IN 46254	
Information Number: (800) 374-1600	Emergency Number: (800) 374 -1600

Section I – Product Identification

Product Name: Carve & Cast	Product Class: Craft	Product Size: 5 lbs, 10 lbs, 25 lbs
Dick Blick Carve & Cast		

Section II – Hazardous Ingredients

Reportable Components	CAS#	Vapor Pressure Mm Hg @ Temp	Weight Percent
------------------------------	-------------	--	---------------------------

No reportable Hazardous ingredients.

This product carries the "AP Seal. Labeling conforms to ASTM D4236/LHAMA.

Section III – Physical / Chemical Characteristics

Boiling Range: NA	Specific Gravity (H2O=1): Less than 2
Vapor Density: Heavier than air.	Evaporation Rate: NA
Coating V.O.C.: NA	Material V.O.C.: NA
Appearance & Odor: White dry blend.	

Section IV – Fire and Explosion Hazard Data

Flash Point: NA	Method Used: NA
Flammable Limits in Air by Volume: No – Lower	No – Upper
Extinguishing Media: No fire hazard.	
Special Firefighting Procedures: None. No fire hazard	
Unusual Fire and Explosion Hazard: None. No fire hazard.	

Section V – Reactivity Data

Stability: Stable	Conditions to Avoid: None
Incompatibility (Materials to Avoid): None	
Hazardous Decomposition or Byproducts: Will not occur.	
Hazardous Polymerization: Will not occur.	

Section VI – Health Hazards

Inhalation Health Risks and Symptoms of Exposure: None.		
Skin and Eye Contact Health Risks and Symptoms of Exposure: None		
Skin Absorption Health Risks and Symptoms of Exposure: None		
Ingestion Health Hazards and Symptoms of Exposure: None		
Health Hazards (Acute / Chronic): No hazardous ingredients.		
Carcinogenicity: No – NTP Carcinogen	No – IARC Monographs	No – OSHA Regulated

Page 2
Carve & Cast

Medical Conditions Generally Aggravated by Exposure: Unknown.
Emergency and First Aid Procedures: Contact you local poison control for further health information.

Section VII – Handling and Use

Steps to Be Taken In Case Material Release or Spill: Clean with paper towels, sponge water & soap.

Waste Disposal Method: Dispose of paper towels in trash and rinse sponges. In manufacturing, dispose of in accordance to Local, State or Federal regulations.

Precautions to Be Taken in Handling and Storing: Store in cool dry place. Do not leave open to moisture will start to cure product.

Other Precautions: Mix dry materials prior to measuring what is to be used.

Section VIII – Control Measures

Respiratory Protection: Not needed.
Ventilation: Not needed.
Protective Gloves: Not needed.
Eye Protection: Not needed
Other Protective Clothing or Equipment: Not needed.
Work / Hygienic Practices: NA

Section IX – Disclaimer

Information presented herein has been compiled from sources considered to be dependable and is accurate and reliable to the best of our knowledge and belief but is not guaranteed to be so. Since conditions of use are beyond our control we make no warranties, expressed or implied, except for those that may be contained in our written acknowledgement.

Prepared by: L. Jenkins
1/2010